		T-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C	_April 28, 2022
DATE	RECORDING TACH/	TOTALTI	
DAIC	HOUR METER TIME	IN SERVI	
			- Engine PBS TJ-100, Serial #076, Engine Time since Factory Overhaul 45.7
			Hours, Engine starts 110
			Next engine Inspection due at 300 hours hobbs time.
			I certify that this aircraft has been inspected in accordance with the scope and detail
		3	of appendix D to part 43, and found to be in a condition for safe operation
			I certify that this aircraft has been inspected in accordance with a yearly condition inspection.
			I certify that this aircraft engine has been inspected in accordance with the {Operation and Maintenance Manual – Turbojet Engine TJ-100 Prepared by PBS Velka Bites, a.s., dated April 2008}, and found to be in a condition for safe operation.
-		Sea.	Mike Fishburn A&P 21485591A
			Mike Fisher
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

10 | EAA Experimental Aircraft Airframe Logbook

Donance Country - New Mexico 5/27/2022
Michaela a allen (2)

